

1

488.2V4 Change History

1.0 INTRODUCTION

This document lists the change history for the 488.2V4 Driver Library.

2.0 CHANGES

Revision	Date and Change
4.0.0.0	04-14-11*Initial release
4.1.0.0	08-23-11*Added a 64-bit GPIB-32.dll that can address the whole 64-bit address space. Replaced the original Spy program with an improved, GUI based Spy program. Added 64-bit versions of our utility programs, demo programs and drivers. All utilities and demo programs are now available in 32 and 64-bit versions.
4.2.0.0	01-30-13*Fixed a memory leak problem.
4.3.0.0	03-01-13*Added Windows 8 to the Driver Library
4.4.0.0	05-11-17*Added new signing certificate for Windows 10.
4.4.0.1	12-11-17*Corrected 64-bit installation problems for Windows 10, fixed the ICS Explorer Configuration page so it can correctly change gpibn name assignments and corrected the GPIB-32.DLL so it correctly terminates a Read on just the EOM character.